

51-4 STANDARDIZATION CHECK

TYPE: High Altitude and Nephography

DURATION: As required

1. Purpose: To further familiarize the pilot with Navigation, Nephography and aircraft control at very high altitudes and complete formal standardization check.

2. Requirements:

a. Take-off, drop pegs, Nephograph covers, and turn on required equipment.

Climb on briefed route to cruising altitude.

b. Cruise climb on briefed route.

c. Accomplish one (1) day celestial navigation leg.

NOTE: Four (4) celestial observations will satisfy the requirements of 51-4 check.

d. Accomplish one (1) DR navigation leg.

e. Accomplish a combination of Nephographic activity so to equal four (4)

Vertex Center and Three (3) Squall Lines.

f. Exercise back-up Nephographic equipment as briefed.

g. Make jet penetration on local beacon.

h. Accomplish one (1) full stop landing.

NOTE: The above accomplishments are minimum activity. All scheduled activity will be considered a part of the 51-4 check.